

9. Scrutinising the pension papers of the retired officers of the Department.
10. The control of the accounts section of the Director's Office.

Irrigation tanks.

31. *MR. S. NILAKANTA PILLAI (*Chirayinkil II*): Will the Government be pleased to place on the table a list containing the number of irrigation tanks improved or newly constructed in each of the taluks of Neyyattinkara, Trivandrum, Nedumangad and Chirayinkil?

MR. G. B. E. TRUSCOTT (*Chief Engineer*): The * list required by the member is placed on the table.

Irrigation tanks in the Chirayinkil taluk.

32. *MR. S. NILAKANTA PILLAI (*Chirayinkil II*): Will the Government be pleased to call for and place on the table a pakuthi-war statement of the irrigation tanks in the Chirayinkil taluk?

MR. G. B. E. TRUSCOTT (*Chief Engineer*): The † statement is laid on the table.

Irrigation works in the Chirayinkil taluk.

33. *MR. S. NILAKANTA PILLAI (*Chirayinkil II*): Will the Government be pleased to state the amount that has been spent towards the irrigation works in the Chirayinkil taluk for the last six years?

MR. G. B. E. TRUSCOTT (*Chief Engineer*): Nil.

MR. S. NILAKANTA PILLAI (*Chirayinkil II*): May I know from the member whether the necessity of attending to any irrigation work in the Chirayinkil taluk was brought to the notice of the Department?

MR. G. B. E. TRUSCOTT (*Chief Engineer*): Not that I am aware of.

Expenditure on the Temple-Entry Committee.

34. *MR. KAINIKKARA M. PADMANABHA PILLAI (*Changanachery I*): With reference to the assurance given by the President on 26-5-34 in reply to my statement about the discrepancy between the answers given by the Chief Secretary on 16-11-33 and 25-5-34 about the expenditure on the Temple-Entry Committee, will the Government be pleased to state:

- (a) how this discrepancy arose; and
- (b) what the real expenditure is?

MR. R. NILAKANTA PILLAI (*Financial Secretary to Government*):

- (a) It was due to a clerical mistake.
- (b) The total expenditure on the Temple-Entry Enquiry Committee up to the end of Edavam 1109 is Rs. 25,529-16-10.

E. S. L. C. Examination.

35. *MR. KAINIKKARA M. PADMANABHA PILLAI (*Changanachery I*): Will the Government be pleased to state:

*Vide Appendix I.

† Vide Appendix II.

tobacco at the harbours of Quilon and Alleppey in 1106, 1107 and 1108 was excluded in effecting the division of income from the Cochin Harbour among the three Governments?

RAO SAHIB DR. N. KUNJAN PILLAI (*Chief Secretary to Government*): Government consider that a discussion on this matter is not in public interests.

Appendix i.

[*Vide Answer to Question No. 31.*]

LIST OF IRRIGATION TANKS.

Neyyattinkara.

- | | |
|----|---|
| 1 | Improvements to Veyomkulam in Kulathur pakuthi. |
| 2 | Do. Vattayoorkulam in Chengal pakuthi. |
| 3 | Certain works to Venjakulam Do. |
| 4 | Improvements to Puthukulam Do. |
| 5 | Do. Ayrialkulam in Kulathur pakuthi. |
| 6 | Do. Karunalkulam Do. |
| 7 | Do. Pulyoorkulam in Chengal pakuthi. |
| 8 | Do. Odathalakulam in Kulathur pakuthi. |
| 9 | Do. Dry rubble pitching on the western bund and widening thodu. |
| 10 | Do. Vembannikarakulam in Neyyattinkara pakuthi. |
| 11 | Do. Karakal kulam in Parassala pakuthi. |
| 12 | Do. Panangottukulam in Kulathur pakuthi. |
| 13 | Do. Venjakulam in Chengal pakuthi. |
| 14 | Do. Vazhangal kulam in Kulathur pakuthi. |
| 15 | Do. Nedumkulam Do. |
| 16 | Do. Kochakulam in Chenkal pakuthi. |
| 17 | Do. Parachikulam in Athiyannur pakuthi. |
| 18 | Do. Aruthalachikulam in Maruthoor Yelah Neyyattinkara pakuthi. |
| 19 | Do. Edakulam in Kulathur pakuthi. |
| 20 | Do. Azhakikulam in Chengal pakuthi. |
| 21 | Do. Thalayarathankonathukulam in Athiyannur pakuthi. |
| 22 | Do. Venkulam in Neyyattinkara pakuthi. |
| 23 | Do. Karumkutty kulam in Parassala pakuthi. |
| 24 | Do. Mangottukonathu kulam in Neyyattinkara pakuthi. |
| 25 | Do. Pudhukulam in Parassala pakuthi. |
| 26 | Do. Thatchikulam in Neyyattinkara pakuthi. |
| 27 | Do. Thevar kulam in Athiyanloor pakuthi. |
| 28 | Do. Vellarachira in Do. |
| 29 | Do. Ponkuzhikulam in Kulathur pakuthi. |
| 30 | Do. Vellaral kulam Do. |
| 31 | Do. Vazhottu kulam in Parassala pakuthi. |

- 32 Improvements to Odappakulam in Parassala pakuthi.
- 33 Do. Vettuvelikulam in Thiruvellam pakuthi.
- 34 Do. Navakottukulam in Marauvalloor pakuthi.
- 35 Do. Nallassery kulam in Neyattinkara pakuthi.
- 36 Do. Nedumkulam in Chengal pakuthi.
- 37 Do. Chavallorkulam Do.
- 38 Do. Chirakulam and Mavarakulam in Parassala pakuthi.
- 39 Do. Kussakottukulam in Neyyattinkara pakuthi.
- 40 Do. Kaniyankulam Do.
- 41 Do. Vadakoḍu Sasthancoil kulam Do.
- 42 Do. Velankonathukulam in Pallichal pakuthi.
- 43 Do. Kattukulam in Nemom pakuthi.
- 44 Do. Neppupuravu kulam in Marukil pakuthi.
- 45 Do. Puthukulam in Athiyanloor pakuthi.
- 46 Restoration of Mampazhachira in Marukil pakuthi.
- 47 Do. Mullalikonathukulam in Neyyattinkara pakuthi.
- 48 Do. Vilangarakonathukulam in Perumkadavila pakuthi.
- 49 Do. Kannankottukulam in Parassala pakuthi.
- 50 Do. Cheriakonathu kulam in Athiyanloor pakuthi.
- 51 Do. Muttakattu Nallakulam in Thiruvallam pakuthi.
- 52 Do. Marthandom Puthukulam in Thiruvallam pakuthi.
- 53 Do. Theyannoor kulam in Kollayil pakuthi.
- 54 Do. Perumparakottukulam in Pallichal pakuthi.
- 55 Do. Edaneerkulam in Chengal pakuthi.
- 56 Do. Thozhukottukonathu kulam in Perumkadavila pakuthi.
- 57 Do. Parakottukonathukulam in Neyyattinkara pakuthi.
- 58 Do. Kuthakottukulam in Neyyattinkara pakuthi.
- 59 Do. Kumarakulam in Kollayil pakuthi.
- 60 Do. Perinkottukulam in Chengal pakuthi.

Nedunangad.

- 1 Restoration of Kulavikonathuchira in Nedumangad taluk.

Chirayinkil.

Nil.

Trivandrum.

- 1 Restoration of Vayambakonathu chira in Ulloor pakuthi.
- 2 Do. Payanga chira in Kadagampally pakuthi.
- 3 Do. Kollumurikulam in Attipara pakuthi.
- 4 Do. Thatchikottukonathukulam in Do.
- 5 Do. Manalikulam in Uliathra pakuthi.

6	Restoration of Kannampallikonam chira in Pangapara pakuthi.
7	Do. Ooruparakulam in Oolloor pakuthi.
8	Do. Achilottuchira in Pangapara pakuthi.
9	Do. Avukulam in Uliathura pakuthi.
10	Do. Vailoor konathukulam in Madathuvilakom pakuthi.
11	Do. Perumanakonathu chira in Pangapara pakuthi.
12	Do. Kosavarkonathu kulam in Vilappil pakuthi.
13	Do. Kodiyilkulam in Pangapara pakuthi.
14	Do. Pullayakonamechira Do.
15	Do. Venkottukonathukulam Do.
16	Do. Ponakottukonathuchira Do.
17	Do. Eravipurathuchira in Oolloor pakuthi.
18	Do. Serakulam in Vanchiyoore pakuthi.
19	Do. Puliyaikonathuchira in Uliathara pakuthi.
20	Do. Kannottukonathu chira in Cheruvikal pakuthi.
21	Do. Kuzhikunnathu chira in Oolloor pakuthi.
22	Do. Iranjalikonam chira in Pangapara pakuthi.
23	Do. Thuzhikonathu kulam in Cheruvikal pakuthi.
24	Do. Kulamangalathu kulam in Oolloor pakuthi.
25	Do. Kallattu chira in Chettivilakom pakuthi.
26	Do. Oorukonathu kulam Do.
27	Do. Perakulam Do.
28	Do. Maranjali chira in Oolloor pakuthi.
29	Do. Paracottukulam Do.
30	Do. Alapurathukulam in Madathuvilakom pakuthi.
31	Do. Cherukarakonathukulam Do.
32	Do. Kavalloorkonathu kulam Do.
33	Do. Mazhanchira kulam in Cheruvikal pakuthi.
34	Do. Serakulam in Vanjiyoore pakuthi. Providing the wall.
35	Do. Nedukoli chira in Oolloor pakuthi.
36	Do. Azhankonathukulam in Madathuvilakom pakuthi.
37	Do. Uliyanathu kulam in Chettivilakom pakuthi.
38	Do. Kunnathu kulam in Chettivilakom pakuthi.
39	Do. Melanconnathu kulam in Madathivilakom pakuthi.
40	Do. Parakottukonathu kulam in Uliathra pakuthi.
41	Do. Puthukolam in Cheruvikal pakuthi.
42	Do. Mettukonathu kulam in Andoorkonam pakuthi.

- 43 Restoration of Oodayattukonam tank in Anchamada
pakuthi.
- 44 Do. Muttamparambathu kulam in Cheruvikal
pakuthi.
- 45 Do. Karuvakonathu kulam in Randamada
pakuthi.
- 46 Do. Parambukonathukulam in Uliathra
pakuthi.

Appendix ii.

[vide Answer to Question No. 32.]

List of Irrigation tanks in the Chirayinkil taluk.

Pakuthi.	Survey		Whether tank or Chira.
	No.	Letter.	
Chirayinkil	2127	25	Pazhachita.
Azhoor	1453		Kulam.
Kundalnr	900		Do.
	569		Do.
	990		Do.
	2381		Chira.
	1850		Kulam.
Kilyallam	598		Chira.
	996	D	Do.
	996	H	Do.
	1037	B	Kulam.
	1045		Chira.
	1095		Kulam.
	1580		Chira.
	1880		Do.
	1881		Do.
	2381		Do.
	2393		Do.
	2472		Do.
	2546		Do.
	2779	B	Kulam.
	2834	A	Chira.
	2860		Kulam.
	2999	7	Chira.
	2999	16	Do.
	3461		Do.
Kadakkavur	1327		Kulam.
Manamboor	314	A	Chira.
	343		Do.
	477	B	Do.
	1500		Kulam.
	2000		Do.
	2036		Do.
	2171		Do.
	2710		Do.
	3636		Do.